


FIG. 1 A



**FIG. 2**




FIG. 3 A





FIG. 3 B




**DP-305538**

Delphi Technologies, Inc., Troy, MI

4/11



**FIG. 4**



**FIG. 5**




FIG. 6




FIG. 7

6/11




FIG. 8

CONTACT BETWEEN THE GROOVE OF THE HOUSING AND THE OUTER ROLLER AT THE OPPOSITE SIDE OF THE LOADED SIDE






FIG. 9



**DP-305538**

Delphi Technologies, Inc., Troy, MI







**DP-305538**

Delphi Technologies, Inc., Troy, MI

8/11



**FIG. 12**



**FIG. 13**







**DP-305538**

Delphi Technologies, Inc., Troy, MI

9/11



**FIG. 14**




**FIG. 15**  
PRIOR ART

**DP-305538**


Delphi Technologies, Inc., Troy, MI

10/11



**FIG. 16**

PRIOR ART




**FIG. 17**


PRIOR ART



11/11



**FIG. 19**  
PRIOR ART



**FIG. 18**  
PRIOR ART